

Oil Field Environmental Incident Summary

Incident: 20151003100622 **Date/Time of Notice:** 10/03/2015 10:06

Responsible Party: Polar Midstream, LLC

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: P VANCE 154-97-14-9

Field Name: TRUAX

Well File #: 29092

Date Incident: 10/1/2015 **Time Incident:** 16:45

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 97

Sec: 9

Qtr:

Location Description: A small amount of crude oil was discovered on the ground near the riser on the Whiting Vance 154-97-14-9 Well Pad. The Coordinates of the location are 48.17031081, -103.15681616.

Submitted By: Jonathan Shares

Received By:

Contact Person: Andrew Parisi
5831 123rd Drive NW
Epping, ND 58843

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1.8	Barrels	1.8	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

This spill did not have the potential to impact surface waters.

Areal Extent:

The spill was contained inside the earthen berm.

Potential Environmental Impacts:

The spill impacted the soil on location. The impacted soil will be excavated and removed from the location. This spill did not have the potential to impact surface waters.

Action Taken or Planned:

The air eliminator valve will be removed and the inlet section of pipe will be replaced to prevent future occurrences.

Wastes Disposal Location: Recovered waste and impacted soil will be hauled to a licensed disposal facility in the area.

Agencies Involved:**Updates**

Date: 10/5/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained on location according to the report. NDIC retains oversight.